


Statistical analysis: Design orthogonality



Measure : abs. value of cosine of angle between columns of design matrix
Scale : black – colinear (cos=+1/-1)
 white – orthogonal (cos=0)
 gray – not orthogonal or colinear